

	Type	Hits	Search Text	DBs	Time Stamp
1	IS&R	382	(228/245).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:39
2	IS&R	482	(228/246).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:37
3	IS&R	592	(228/33).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:37
4	IS&R	417	(228/41).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:37
5	IS&R	3993 7	("228").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:39
6	IS&R	1801 06	("29").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:39
7	BRS	2130 41	S5 or S6	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:39
8	BRS	952	S7 and ((solder or ball\$1) near20 (vacuum or suction)) and (force or pressure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:42
9	BRS	27	S7 and ((solder or ball\$1) near20 (vacuum or suction)) and ((force or pressure) near50 \$6balanc\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:42

	Type	Hits	Search Text	DBs	Time Stamp
10	BRS	318	S7 and ((solder or ball\$1) near20 (vacuum or suction)) and ((force or pressure) near50 (\$6balanc\$3 or position\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:43
11	BRS	267	S7 and ((solder or ball\$1) near10 (vacuum or suction)) and ((force or pressure) near20 (\$6balanc\$3 or position\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:43
12	BRS	47	S7 and (((solder or ball\$1) near10 (vacuum or suction)) near200 ((force or pressure) near20 (\$6balanc\$3 or position\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:43
13	BRS	47	S7 and (((solder or ball\$1) near10 (vacuum or suction)) near100 ((force or pressure) near20 (\$6balanc\$3 or position\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:47

	Type	Hits	Search Text	DBs	Time Stamp
14	BRS	268	(((solder or ball\$1) near10 (vacuum or suction)) near100 ((force or pressure) near20 (\$6balanc\$3 or position\$3)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/01/18 14:47